

SCALE







**TRAVE
SALA**





















A photograph showing a ceiling with a hole. The ceiling is made of concrete or plaster and has some discoloration and a large hole on the right side. A metal beam is visible on the right. A label with an arrow points to a small hole on the left. The label contains the text:

**CUCINA
CANNA
FUMARIA PER
CAPPA**

110



**TRAVE LESIONATA
SOSTITUITA E
CONSERVATA IN
CANTIERE**









**BAGNO
SISSY**



**BAGNO
SISSY**







**CANNA SOPRA
NICCHIA ARCO
BAGNO SISSY**





PAISE
TUI AT

**CAMERA
MIKY**





**VECCHIA PORTA
CAMERA MIKY**



**MURO RETRO
SANITARI
CAMERA MIKY**









**SOPRA PORTA
BAGNO MIKY**



**BAGNO
MIKY**























**SCARICO
GEGIO (?)**





**SCARICO
GEGIO (?).
RINVENUTI
TRAVETTI
TAGLIATI E
ASSITO
SOSTITUITO.**











**CORRIDOIO
VERSO CAMERA
SISSY**



